

Front View



Rear View





Right Side Loose/broken/delaminated Previous repair Replaced piece Damage/wear/hole


Add-ons Missing Spindles not original to desk Inscriptions


Left Side

Top













Bottom


Bottom





Drawer Front, Outer Surface

Rear Surface of Drawer Front













Inside Surface of Left Drawer Side


Inside Surface of Right Drawer Side





Rear Surface of Drawer Back


Front Surface of Drawer Back














Upper Surface of Drawer Bottom

Lower Surface of Drawer Bottom



Outside Surface, Right Drawer Side

Outside Surface, Left Drawer Side

